Microsoft Visual Studio

HINT: Not all types of devices can be found automatically

OK   Cancel

Microsoft Visual Studio

Scan for boxes

Yes   No

EtherCAT drive(s) added

Append linked axis to: ● NC - Configuration   OK

CNC - Configuration   Cancel

LATCOS